

Test Report No.: SDHL1606010781FT Date: Jul.01, 2016 Page 1 of 3

The following sample(s) was / were submitted and identified on behalf of the client as:

Sample Receiving Date : Jun.21, 2016

Test Performing Date : Jun.21, 2016 to Jul.01, 2016

Test Result Summary

Too, House, Culturally	
Test(s) Requested	Result(s)
Gas spring durability test (80,000 cycles)	PASS
Summary:	
 For further details, please refer to the following page(s). 	

Signed for and on behalf of Shunde Branch SGS-CSTC Co., Ltd.

Bill Wang Approved signatory





This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: Ch. Doccheck@sss.com

15.1 Bilding Burgoen Industrial Park No.1 Sturpteren Road Wilsta Section Dalarin Town Shands Frishin Guaroping Clima 528333 1 (86-757)22805888 1 (86-757)22805858 www.sgs.group.com.cn 中国·广东·佛山市顺德区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757)22805888 f (86-757)22805858 e sgs.china@sgs.com



Test Report No.: SDHL1606010781FT Date: Jul.01, 2016 Page 2 of 3

TESTS AND RESULTS

Test Conducted:

Gas spring durability test as per client's requirements

General Test Condition:

The following test program was conducted in a laboratory environment maintained at 15 ℃ to 25 ℃ and 50%±5 RH. The sample was individually tested after conditioning in the test environment for at least 24 hours prior to conducting the test.

The complete detailed procedures may be found in the referenced specification and are only summarized herein.

No. of Sample:

1 piece(s) (Sample 1). For more sample information and pictures, please refer to the following page.

Test Description and Requirements	Test Results
Gas spring durability test	
Mount the gas spring to be tested to the testing machine and keep the piston downward;	
2. Compress the piston to the position 10mm from the fully compressed and then release it, this process constitutes one cycle;	PASS
3. Operate the gas spring for a total number of 80,000 cycles at a rate of 15 cycles per minute;	
4. After test, no loss of serviceability and oil leaking shall be found.	

Remark:

For the sample information and pictures, please refer to the following page.



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's scle responsibility is to its Client and this document does not sonerate parties to a transaction fore varieties and biligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@sss.com

1/F, 1 Building, Europein Industrial Part, No.1. Stumberen Road, Wuste Section Daterry Town, Shunde, Fishan, Guangdonn, Clina 528333 t (86-757)22805888 f (86-757)22805858 www.sgsgroup.com.cn 中国·广东·修山市原德区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层 邮编: \$28333 t (86-757)22805888 f (86-757)22805858 e sgs.china@sgs.com



Test Report No.: SDHL1606010781FT Date: Jul.01, 2016 Page 3 of 3

SAMPLE INFORMATION AND PICTURES

Weight: 65.0 g

Overall Dimensions: 228.59 mm (L) x 5.96 mm (Dia.) x 14.86 mm(Dia.)

Other Dimensions: /

Sample as Received





End of Report



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's scle responsibility is to its Client and this document does not oxnoreate parties to a transaction from exercicing all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@sss.com

1F,1' Bulding, European Industrial Park, No.1 Sturmieren Road, Musta Secton Dalarry Town, Shunda, Fishan, Guargotin, China \$28333 1 (86-757)22805888 1 (86-757)22805858 www.sgsgroup.com.cn 中国・广东・修山市原徳区大良街道か事处五沙原和南路1号欧洲工业园一号厂房首层 邮编: 528333 t (86-757)22805888 f (86-757)22805858 e sgs.china@sgs.com